

Errata Tarion-1

Rev	Date/Signature	Changes
1	21.05.2014/Ko	First Revision

1 Product affected

Product affected	Rev.
DIMM-EcoBase Tarion	R1B

2 Errata 1 – EDT Display connector J33

2.1 Description

The generic Display interface over the EDT Family Connector don't work because the display clock of some Displays are inverted on the Display Adapter Board.

2.2 Projected Impact

The EDT Display Connector is not available on DIMM-EcoBase Tarion R1B.

2.3 Workaround

Remove Display Clock inverter on the EDT Display Adapter.

2.4 Proposed Solution

This issue will be fixed at DIMM-EcoBase Tarion R2A boards.