

Product Change Notice – PCN_DIMM-MX6-5_R5A

Rev	Date/Signature	Changes
1	11.07.2014/Sr	First Revision

1 Product affected

Product affected	Rev.	Replacement	Rev.
DIMM-MX6Q-4-1G-2G	R4	DIMM-MX6Q-5-1G-2G	R5A
DIMM-MX6Q-4-1G-2G-ET	R4	DIMM-MX6Q-5-1G-2G-ET	R5A
DIMM-MX6D-4-1G-2G	R4	DIMM-MX6D-5-1G-2G	R5A
DIMM-MX6D-4-1G-2G-ET	R4	DIMM-MX6D-5-1G-2G-ET	R5A
DIMM-MX6S-4-1G-2G	R4	DIMM-MX6S-5-1G-2G	R5A
DIMM-MX6S-4-1G-2G-ET	R4	DIMM-MX6S-5-1G-2G-ET	R5A

2 Change 1 – Production Improvements

2.1 Key Characteristics of the Change

Patches which was done manually are included into the PCB design.

2.2 Description of Change to the Customer

To improve production process and the product quality the patches of revision R4B are now included into the PCB design.

2.3 Costumer Impact of Change and Recommended Action

No actions necessary.